Work Order ID 105629

105629

August-09-13 2:33:16 PM

Item ID: DSI 9279-011 **Accept** *N900040100* **Setup Start** *NS1*

Revision ID: **Stop** *NS2*

Item Name: Strobe Power Supply Relocation

Start Date: 8/08/13 **Start Qty:** 1.00 *1*

Required Date: 8/09/13 **Req'd Qty:** 1.00 *1*

Reference: RMA RA111572 RETURN-SCRAP

Cust Item ID:

Customer: CAERO55

Run Start *NR1*

Stop *NR2*

Approvals: **Process Plan:** ✓ **Date:** **Tooling:** **Date:**

QC: **Date:** **SPC (Y/N):** **Date:**

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr: D3246	Revision Nbr: Rev A1								
100		0.00							
100									
QC	**Memo**	0.00							
Quality Control	INSPECT RA111572 1 X DSI9279-011 B92126 CHG001								
110		0.00							
110						1	0		JMJ 8-08-13
Small Fab	**Memo**	0.00							
Small Fab	SCRAP/DESTROY D3246-041								
120	QC21- Final Inspection - Work Order Release	0.00							
120									13/8/2013
QC	**Memo**	0.00							
Quality Control									

DAS 16 9-8 13/08/13

MJ 13-08-13

Picklist Print

August-09-13 2:33:16 PM

Work Order ID: 105629

Parent Item: DSI 9279-011 **Start Date:** 8/08/13 **Required Date:** 8/09/13

Parent Item Name: Strobe Power Supply Relocation **Start Qty:** 1.00 **Required Qty:** 1.00

Comments: IPP B04.02.26Add D3121-141 to Step 3KJ/DS

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
DSI 9279-011		Manufactured	No				Each	1.0000		1			
Strobe Power Supply Relocation													

Location	Loc Qty	Loc Code
FG033	1	
102737	1	

Jm 13-08-19

92126

RA 111572 DSI 9279-011 B92126

Received @ Dart July 30th, 2013
Inspected@ Dart August 6th, 2013

CUSTOMER: AS AEROSPACE LTD
CUSTOMER CONTACT: LEE SHAW
SHIPPED FROM: DENHAM UXBRIDGE, UK

Instructions for RA 111572 DSI 9279-011 B92126 CHG001

- Scrap D3246-041 cost of rework over that cost of part
- Need work order for scraping part

Time Estimate = 1 HOUR
Departments Required: Quality Control
Pictures Attached = NO
QTY INSPECTED = x1 D3246-041 B79827

THIS INSTRUCTION SHEET MUST BE ATTACHED TO THE RESTOCKING WORK ORDER AT ALL TIMES!!!!